
Concrete Columns (ACI 318)

- Types of columns
- Tied columns
- · Spiral columns
- · Interaction diagrams
- 3d printed forms





University of Michigan, TCAUP Structures II Slide 1 of 16

Compression Members

- Pedestals are compression members with an aspect less than or equal to 3:1. They can be used without reinforcing.
- Columns are any more slender members which carry primarily axial compressive loads.
- Columns always require reinforcing ACI 318-19 section 10.6.1
- Minimum reinforcing to insure ductile failure:
 1% i.e. As/Ag ≥ 0.01
- Maximum reinforcing to prevent blockage: 8% i.e. As/Ag ≥ 0.08 in practice 4% is better.








Types of Columns

There are 3 types of columns based on how they are reinforced:

- 1. tied column (a)
- 2. spiral column (b)
- 3. composite column (c & d)



University of Michigan, TCAUP

Structures II

Slide 3 of 16

Column Reinforcing Tied Columns

The ties restrain the expansion of the core concrete and the outward buckling of the longitudinal bars.

Longitudinal bars:

minimum for square columns is 4. minimum for round columns is 6. maximum spacing is 6"

Ties:

no less than #3 with #10 or less longitudinal steel.

no less than #4 with #11 and greater longitudinal steel.

tie spacing is the least of:

- 16 x longitudinal bar diameter
- 48 x tie diameter
- · least width column

crossties brace alternate longitudinal bars or bars > 6" o.c.




Figure 8.3 Typical Tie Arrangements


Column Reinforcing Spiral Columns

Clear spacing (the pitch, s) should be between 1" and 3"

spiral should be continuous or spliced must be welded or overlapped.

spacers (vertical bars with hooks) are used to hold spirals in place during casting.

Spiral columns are more ductile in failure and stronger than tied columns (by about 5%)





University of Michigan, TCAUP Structures II Slide 5 of 16

Column Design Considerations

High strength concrete is more effective than in beams.

Because steel is more expensive, it is better to increase column size and reduce steel needed.

Tied columns (particularly rectangular) are more economical than spiral.

But spiral columns with high strength concrete reduce column size.

Larger bar sizes reduce congestion when casting. Bars can also be bundled.



Column Modes of Failure

Stress distribution between steel and concrete varies under load and time, but ultimate failure is more predictable.

For design, failure is defined as the spalling of the cover concrete.

Even with the cover cracked the column will continue to carry load.

Spiral columns are tougher than tied


A column is a more critical member. It supports a greater area. Therefore the Φ factor is lower.

 Φ = 0.65 for tied columns

 Φ = 0.75 for spiral columns


Also:

columns are more difficult to cast, and concrete carries more of the load than in beams



Structures II

Slide 7 of 16



Reduced Nominal Strength ≥ Factored Load Effects

ΦSn ≥ U

γ Factored Loads (see ACSE 7)

1) 1.4D

2) 1.2D + 1.6L + 0.5(Lr or S or R)

3) 1.2D + 1.6(Lr or S or R) + (1.0L or 0.5W)

4) 1.2D + 1.0W + 1.0L + 0.5(Lr or S or R)

5) 1.2D + 1.0E + 1.0L + 0.2S

6) 0.9D + 1.0W

7) 0.9D + 1.0E

D = service dead loads

L = service live load

Lr = service roof live load

S = snow loads


W = wind loads

R = rainwater loads

E = earthquake loads

Strength Reduction Factors, Φ

Mn	Flexural (€ > 0.005)	0.90
Vn	Shear	0.75
Pn	Compression (spiral)	0.75
Pn	Compression (other)	0.65
Bn	Bearing	0.65
Tn	Torsion	0.75
Nn	Tension	0.90
Combin	ed stress	0.65 to



Axial Strength Calculation

Po is the nominal axial strength with no eccentricity.

Pn,max is Po with a factor for minimum moment

For spiral and composite columns:

$$P_u = \Phi P_n = \Phi 0.85 [0.85 f'c (A_g - A_s) + f_y A_s]$$

For tied columns:

$$P_u = \Phi P_n = \Phi 0.80 [0.85 f'c (A_g - A_s) + f_y A_s]$$

22.4.2 Maximum axial compressive strength

22.4.2.1 Nominal axial compressive strength P_n shall not exceed $P_{n,max}$ in accordance with Table 22.4.2.1, where P_o is calculated by Eq. (22.4.2.2) for nonprestressed members and composite steel and concrete members, and by Eq. (22.4.2.3) for prestressed members.

Table 22.4.2.1—Maximum axial strength

Member	Transverse reinforcement	$P_{n,max}$	
	Ties conforming to 22.4.2.4	0.80P _o	(a)
Nonprestressed	reinforcement	0.85P _o	(b)
P	Ties	0.80P _o	(c)
Prestressed	reinforcement $P_{n,max}$ Ties conforming to 22.4.2.4 $0.80P_a$ Spirals conforming to 22.4.2.5 $0.85P_a$ Ties $0.80P_a$ Spirals $0.85P_a$	0.85P _o	(d)
Composite steel and concrete columns in accordance with Chapter 10	All	0.85P _o	(e)

22.4.2.2 For nonprestressed members and composite steel and concrete members, P_o shall be calculated by:

$$P_o = 0.85f_c'(A_g - A_{st}) + f_v A_{st}$$
 (22.4.2.2)

where A_{st} is the total area of nonprestressed longitudinal reinforcement.


University of Michigan, TCAUP

Structures II

Slide 9 of 16

Axial Strength Design (no moment) Tied Column Procedure

- 1. Find factored axial load Pu (apply λ factor for load case).
- 2. Choose $\rho = As/Ag (0.01 \text{ min.}, 0.08 \text{ max.})$
- 3. Find concrete Ag based on ρ As = ρ Ag $P_u = \Phi$ $P_n = \Phi 0.80$ [0.85f'c (A_g - A_s) + f_y A_s]
- 4. Choose column section based on Ag
- Find steel As based on concrete Ag. Choose bar size and number
- Determine tie size.
 for longitudinal bar ≤ #10 use #3 ties
 for > #10 or bundled bars use #4 ties
- 7. Find tie spacing. use the least of:
 - a) 48 x tie diameter
 - b) 16 x longitudinal steel diameter
 - c) least column dimension
- 8. Check section dimensions.



Axial Strength Design

(no moment)
Tied Column Example

Given: $P_{DL} = 200 \text{ k} P_{LL} = 300 \text{ k}$

f'c = 4000 psi fy = 60 000 psi

Required: column size and reinforcement

- 1. Find factored axial load Pu (apply λ factor for load case).
- 2. Choose ρ = As/Ag (0.01 min., 0.08 max.) assume ρ = 0.02 (good economically).
- 3. Find concrete Ag based on ρ $P_u = \Phi P_n = \Phi 0.80 [0.85 f'c (A_g-A_s) + f_y A_s]$
- 4. Choose column section based on Ag

$$P_{4} = 1.4(200) + 1.7(300)$$

= $280 + 510 = 790^{K}$

$$P_{U} = 40.80[0.85f_{c}^{2}(A_{g}-A_{s})+f_{g}A_{s}]$$

 $\phi = 0.65$ FOR TIED COLUMNS
FOR $\rho = 0.02$ $A_{s} = \rho A_{g} = 0.02$ A_{g}

$$790 = 0.65(0.80) [0.85(4)(Ag - 0.02Ag) + 60(0.02Ag)]$$

$$790 = 2.3566 Ag$$

$$Ag = 335.2 in^{2}$$

University of Michigan, TCAUP

Structures II

Slide 11 of 16

Axial Strength Design

(no moment)
Tied Column Example

5. Find steel As based on concrete Ag. Choose bar size and number

USE
$$Ag = 19 \times 19 = 361 \text{ m}^2$$

FIND As
 $Pu = \phi 0.80 \left[0.85 \text{ f'}_c \left(Ag - As' \right) + \text{ fy } As' \right]$

Axial Strength Design


(no moment) Tied Column Example

- 6. Determine tie size. for longitudinal bar ≤ #10 use #3 ties for > #10 or bundled bars use #4 ties
- 7. Find tie spacing. use the least of:
 - a) 48 x tie diameter
 - b) 16 x longitudinal steel diameter
 - c) least column dimension
- 8. Check section dimensions.

TIE SPACING

- a) 48 × 3/8 = 18" ← USE SMALLEST b) 16 × 1.128 = 18.05"
- C) LEAST DIM. = 19"

USE 18" TIE SPACING



$$S = \frac{19^{''}-2(1.5)-3(1.128)-2(0.375)}{2}$$

$$S = \frac{11.866^{''}}{2} = 5.93^{''}$$

$$6.93^{''} < 6^{''} : \text{No cross Ties}$$

University of Michigan, TCAUP


Structures II


Slide 13 of 16

Axial Strength Design

(no moment) Spiral Column Procedure

- Find factored axial load Pu (apply λ factor for load case).
- Choose ρ = As/Ag (0.01 min., 0.08 max.)
- Find concrete Ag based on ρ $P_u = \Phi P_n = \Phi 0.80 [0.85 f'c (A_q - A_s) + f_v A_s]$ $\Phi = 0.75$
- Choose column diameter based on Ag
- Find concrete core area, Ac = $\frac{\pi D_c^2}{4}$ Dc = diameter of core, out to out of spiral
- Find ρ s min = 0.45 (Ag/Ac -1) f'c/fy ps = ratio of volume of spiral steel to volume of concrete core
- 7. Choose spiral bar size. Minimum = 3/8"
- Determine spiral pitch, $1'' \le s \le 3''$ 8.





FIHD PITCH S:

$$S = \frac{4a_s(D_c - d_b)}{\rho_s D_c^2}$$

IF S < 1" CHOOSE SMALLER BAR IF S > 3" CHOOSE LARGER BAR OR BIGGER COLUMN DIAMETER

Combined Axial + Flexure

Bending moments are almost always present due to columns being continuously cast with beams.

Solutions are normally found using interaction diagrams.


Axial force is on the vertical axis and the flexure moment is the horizontal

Each curve is for a different ρ

Graphs are for specific bar arrangements, f'c and fy

- 1. Choose section dimensions
- 2. Calculate Kn and Rn
- 3. Find ρ
- 4. Determine As = ρ Ag
- 5. Check bar spacing, Ag and ties.

Column Interaction Diagram




University of Michigan, TCAUP Structures II Slide 15 of 16

3D printed / robotic fabrication

difficult to integrate longitudinal steel.

could be used as forms for casting column



ETH, Zurich



Taubman College



Quinta da Boavista SAMF Arquitectos

Structures II

University of Michigan, TCAUP

Slide 16 of 16